



**ARIZONA  
ROCK  
PRODUCTS  
ASSOCIATION**

*Certificate of Conformance  
for  
Hot Mix Asphalt Production Facilities*

It is hereby certified that

Vulcan Materials Co. | 4830 S. 43rd Avenue, Phoenix, AZ | Plant #5182-211

has been inspected by the undersigned registered professional engineer for conformance with requirements of the "Check List for Hot Mix Asphalt Production Facilities." As of the inspection date, the facilities met requirements as stated below.

\_\_\_\_\_  
Signature of P.E.


**Arizona Rock Products Association**

01/02/2015  
\_\_\_\_\_  
Inspection Date

01/26/2015  
\_\_\_\_\_  
Date

01/02/2017  
\_\_\_\_\_  
Certificate Expiration Date

\_\_\_\_\_  
Executive Director



This Company will maintain these facilities in compliance with the Check List requirements and will correct promptly any deficiencies which develop.

Notice: The check list indicates only that plant facilities are satisfactory for the production of asphalt when properly operated. Conformance of the asphalt itself with specification requirements must be verified by usual inspection methods in accordance with sales agreement.