



**ARIZONA
ROCK
PRODUCTS
ASSOCIATION**

***Certificate of Conformance
for
Hot Mix Asphalt Production Facilities***

IT IS HEREBY CERTIFIED THAT
Martin Marietta Plant #13119
3602 N. Higley Road, Mesa, AZ 85215
has been inspected by the undersigned registered professional engineer
for conformance with requirements of the "Check List for Hot Mix
Asphalt Production Facilities." As of the inspection date, the facilities
met requirements for production by

Signature of P.E.
7/28/2022

Inspection Date
7/28/2024

Certificate Expiration Date

ARIZONA ROCK PRODUCTS ASSOCIATION
8/30/2022

Date

President



**This company will maintain these facilities in compliance with the
Check List requirements and will correct promptly any deficiencies which
develop.**

Signature and Title of Company's Principal Executive

NOTICE: The Check List indicates only that plant facilities are satisfactory for the production of concrete when properly operated. Conformance of the concrete itself with specification requirements must be verified by usual inspection methods in accordance with sales agreements.