



**ARIZONA  
ROCK  
PRODUCTS  
ASSOCIATION**

***Certificate of Conformance  
for  
Hot Mix Asphalt Production Facilities***

**IT IS HEREBY CERTIFIED THAT**

*Southwest Asphalt - Plant No. 2 (Florence)*

**has been inspected by the undersigned registered professional engineer for conformance with requirements of the "Check List for Hot Mix Asphalt Production Facilities." As of the inspection date, the facilities met requirements for production by**

*[Signature]*  
\_\_\_\_\_  
Signature of P.E.

*1/17/2022*  
\_\_\_\_\_  
Inspection Date

*1/17/2024*  
\_\_\_\_\_  
Certificate Expiration Date

ARIZONA ROCK PRODUCTS ASSOCIATION

*1/25/22*  
\_\_\_\_\_  
Date

*[Signature]*  
\_\_\_\_\_  
President



**This company will maintain these facilities in compliance with the Check List requirements and will correct promptly any deficiencies which develop.**

*[Signature]* *Operations Manager*  
\_\_\_\_\_  
Signature and Title of Company's Principal Executive

**NOTICE: The Check List indicates only that plant facilities are satisfactory for the production of concrete when properly operated. Conformance of the concrete itself with specification requirements must be verified by usual inspection methods in accordance with sales agreements.**