



ARIZONA
ROCK
PRODUCTS
ASSOCIATION

***Certificate of Conformance
for
Hot Mix Asphalt Production Facilities***

IT IS HEREBY CERTIFIED THAT Southwest Asphalt, Plant 4
6015 N. El Mirage Rd., Glendale, AZ 85307

has been inspected by the undersigned registered professional engineer
for conformance with requirements of the "Check List for Hot Mix
Asphalt Production Facilities." As of the inspection date, the facilities
met requirements for production by

Signature of P.E.

4-2-2025

Inspection Date

4-2-2027

Certificate Expiration Date



ARIZONA ROCK PRODUCTS ASSOCIATION

4-2-2025

Date

President



This company will maintain these facilities in compliance with the
Check List requirements and will correct promptly any deficiencies which
develop.

Signature and Title of Company's Principal Executive

NOTICE: The Check List indicates only that plant facilities are satisfactory for the production of concrete when properly operated. Conformance of the concrete itself with specification requirements must be verified by usual inspection methods in accordance with sales agreements.