



**ARIZONA
ROCK
PRODUCTS
ASSOCIATION**

*Certificate of Conformance
for
Hot Mix Asphalt Production Facilities*

It is hereby certified that

Vulcan Materials Company | Plant #5181-211 | Val Vista

has been inspected by the undersigned registered professional engineer for conformance with requirements of the "Check List for Hot Mix Asphalt Production Facilities." As of the inspection date, the facilities met requirements as stated below.

Signature of P.E.

06/03/2020

Inspection Date

06/03/2022

Certificate Expiration Date

Arizona Rock Products Association

St. Trull

Executive Director

06/03/2020

Date



This Company will maintain these facilities in compliance with the Check List requirements and will correct promptly any deficiencies which develop.

Notice: The check list indicates only that plant facilities are satisfactory for the production of asphalt when properly operated. Conformance of the asphalt itself with specification requirements must be verified by usual inspection methods in accordance with sales agreements.